



Mengenermittlung

Projekt: EBR207 ENB DL K136 Neu Poserin
Aufmaß: EBR207 Kostenberechnung DL Neu Poserin

OZ	K	Messtext	Faktor	FN	Rechenansatz	Ergebnis	Adresse
01.01.0080.				0	1,000 =	1,000	1 C0
01.01.0090.				0	1,000 =	1,000	1 D0
01.02.0010.				0	1,000 =	1,000	1 E0
01.02.0020.				0	1,000 =	1,000	1 F0
01.02.0030.				0	50,000 =	50,000	1 I0
01.02.0040.				0	8,000 =	8,000	1 L0
01.02.0050.				0	5,000 =	5,000	1 M0
01.02.0080.				0	1,000 =	1,000	1 V0
01.02.0090.			2,500	0	30,000 =	75,000	1 W0
01.02.0100.				0	1,000 =	1,000	1 X0
01.02.0110.			2,500	0	30,000 =	75,000	1 Y0
01.02.0120.				0	1,000 =	1,000	1 Z0
01.02.0130.			2,500	0	30,000 =	75,000	2 A0
01.02.0140.				0	1,000 =	1,000	2 B0
01.02.0150.			2,500	0	30,000 =	75,000	2 C0
01.03.0010.				0	1,000 =	1,000	2 D0
01.03.0020.				0	10,000 =	10,000	2 E0
01.03.0030.				0	1,000 =	1,000	2 F0
01.03.0040.				0	2,000 =	2,000	2 G0
01.03.0050.	*	Fläche grafisch ermittelt					2 H0
01.03.0050.		Bankett	0	25,000	* 2,000 * 0,100 * 2,000 =	10,000	2 J0
01.03.0050.		Böschung	0	25,000	* 4,000 * 0,100 * 2,000 =	20,000	2 K0
01.03.0070.		Böschung	0	25,000	* 4,000 * 2,000 =	200,000	2 W1
01.03.0080.		Böschung	0	25,000	* 4,000 * 2,000 =	200,000	2 Y1
01.03.0090.	*	Schichten bis OK DL unter Betonfahrbahn					3 C0
01.03.0090.			0	25,000	* 4,000 * 0,450 =	45,000	3 D0
01.03.0090.			0	2,000	* 25,000 * 0,450 =	22,500	3 E0
01.03.0090.		Rundung	91	2,500=		2,500	3 F0
01.03.0140.		Fahrbahn	0	25,000	* 5,000 =	125,000	3 V0
01.03.0140.		Bankett	0	25,000	* 4,000 =	100,000	3 W0
01.03.0150.			2,000	0	25,000 =	50,000	3 Z0
01.07.0050.				0	4,000 =	4,000	4 N0
01.10.0020.				0	4,000 =	4,000	6 E0
01.10.0030.	*	Fläche grafisch ermittelt					6 Q0
01.10.0030.			0	25,000	* 7,000 * 0,310 =	54,250	6 R0
01.10.0030.		Rundung	91	0,750=		0,750	6 S0
01.10.0040.			0	25,000	* 6,500 =	162,500	6 V0
01.10.0040.		Rundung	91	2,500=		2,500	6 W0
01.10.0060.	E		4	25,000	4,000	100,000	6 Z0
01.10.0070.			0	6Z0 =		100,000	7 C0
01.10.0080.			0	6Z0 =		100,000	7 D0
01.10.0090.			0	6Z0 =		100,000	7 E0
01.10.0100.			0	6Z0 =		100,000	7 F0
01.10.0110.			0	4,000 + 4,000 =		8,000	7 G0
01.10.0110.	P					0,000	7 I0
01.10.0110.					Positionssumme	8,000	7 I0
01.10.0120.			0	8,000 =		8,000	7 J0
01.10.0130.			2,000	0	25,000	50,000	7 K0
01.01.0010.				0	1,000 =	1,000	7 L0
01.01.0020.				0	1,000 =	1,000	7 M0
01.01.0030.				0	1,000 =	1,000	7 O0
01.01.0040.				0	1,000 =	1,000	7 P0
01.01.0050.				0	1,000 =	1,000	7 Q0
01.01.0060.				0	1,000 =	1,000	7 R0
01.01.0070.				0	1,000 =	1,000	7 S0
01.01.0120.				0	1,000 =	1,000	8 C0
01.02.0060.				0	5,000 =	5,000	8 E0
01.02.0070.				0	2,000 =	2,000	8 G0
01.03.0170.				0	2,000 =	2,000	8 H0
01.03.0180.				0	30,000 =	30,000	8 I0
01.03.0190.				0	30,000 =	30,000	8 J0
01.03.0210.				0	2,000 =	2,000	8 L0
01.03.0220.				0	2,000 =	2,000	16 Z0
01.03.0250.				0	2,000 =	2,000	17 E1
01.03.0260.				0	30,000 =	30,000	17 E2
01.06.0010.			91	14,5=		14,500	17 I0
01.01.0100.			91	2=		2,000	17 J0
01.01.0110.			91	2=		2,000	17 K0



Mengenermittlung

Projekt: EBR207 ENB DL K136 Neu Poserin
Aufmaß: EBR207 Kostenberechnung DL Neu Poserin

OZ	K	Messtext	Faktor	FN	Rechenansatz	Ergebnis	Adresse
01.03.0060.		Bankett		0	25,000 * 2,000 * 2,000 =	100,000	17 L0
01.06.0020.			2,000	91	1,5*0,3*1=	0,900	17 T0
01.06.0020.		Rundung		91	0,100=	0,100	17 U0
01.07.0010.				91	17=	17,000	17 V0
01.07.0020.				4	4,000 25,000	100,000	17 W0
01.07.0030.			2,000	91	4=	8,000	17 X0
01.07.0040.				91	2*4=	8,000	17 Y0
01.10.0010.				91	4=	4,000	17 Z0
01.10.0140.			2,000	91	3,5*4-(1,34*1,05)=	25,186	18 A0
01.10.0140.		Rundung		91	2,814=	2,814	18 B0
01.03.0230.				91	20=	20,000	18 C0
01.03.0240.				91	20=	20,000	18 D0
01.03.0100.				5	6,400 3,700 1,350 12,000	81,810	18 E0
01.03.0100.		Rundung		91	8,190=	8,190	18 F0
01.03.0110.				5	3,700 1,000 1,350 17,000	53,933	18 G0
01.03.0110.			- 1,000	7	0,200 400,000 17,000	-2,136	18 H0
01.03.0110.		Rundung		91	3,203=	3,203	18 I0
01.03.0120.				5	6,400 3,700 1,350 12,000	81,810	18 J0
01.03.0120.			- 1,000	7	0,600 400,000 12,500	-14,137	18 K0
01.03.0120.		Rundung		91	2,327=	2,327	18 L0
01.03.0130.				5	3,700 1,000 1,350 17,000	53,933	18 L1
01.03.0130.		Rundung		91	1,067=	1,067	18 M1
01.03.0160.				91	25=	25,000	18 N1
01.08.0010.			2,000	91	2=	4,000	18 O1
01.08.0020.			4,000	91	0,4*0,4*1,2=	0,768	18 P1
01.08.0020.		Rundung		91	0,232=	0,232	18 Q1
01.10.0050.			2,000	0	25,000 * 1,250 =	62,500	18 R1
01.10.0050.		Rundung		91	2,500=	2,500	18 S1