**FAIR - Facility for Antiproton and Ion Research in Europe GmbH**
Planckstraße 1
64291 Darmstadt
www.fair-center.eu

**Test results – Diamond plates**
5.11.2026

The results of the test measurements listed below must be reported.

1. **Size and thickness measurements.** The size and thickness measurements will be repeated at GSI after the delivery for confirmation. If the values are not according to the specifications, the plate will be returned and must be substituted with a good one.
2. **Leakage current.** The measured data points (min. 10 per positive V values and min. 10 per negative V value) of the I – V measurements must be plotted and delivered. If the values are not according to the specifications, the plate will be returned and must be substituted. The I – V measurement will be repeated at GSI after the delivery for confirmation. If the values are not according the specifications, the plate will be returned and must be substituted with a good one.
3. **CCE.** The measurement will be done at GSI after the delivery for confirmation. If the criteria are not satisfied the plate will be returned and must be substituted with a good one.